

# ***Subsea Control Pod Rebuild***

This pod was delivered to us, stripped and in poor condition. After thorough cleaning and inspection, the block was stripped of plating, the defects repaired, and replated. All valves and regulators were rebuilt. A new kidney plate, and latch rod were installed. The pod is now ready for many more years of service.

